

Date: 17 September 2009

Affected Products: FDMR-1 – FlashScan Dual Input, Dual Output Module

System Sensor has identified a potential issue with the Notifier FDMR-1 – Dual Input, Dual Output Modules, whereby a manufacturing defect may cause output relays to either fail to activate or fail to de-activate.

This issue may affect FDMR-1 modules manufactured with serial codes between 9031xxxxx and 9044xxxxx. Please see picture below to identify product serial code.



FDMR-1 modules with the above serial codes should be operationally tested and any which are found to defective should be returned to Notifier for replacement.

If you have any question please do not hesitate to contact me.

Sincerely,



James Edwards
Product Manager