

Date: 16th October, 2007

Affected Products: IFS 993 - Monitored strobe/sounder driver card.

Notifier has now released IFS-993 Rev F which will replace IFS-993 rev B. This new product has the following improvements;

- Removable connectors.
- Able to be double stacked to save space.
- Fits the standard mounting holes for IFS-717 to simplify fitting to panels.
- Fixed reliability issue with toggling fault relays and short circuit LED.
- Able to be driven directly from the bell output of IFS-2600 and AFP-2800.
- Normally energised fault relay for 'fail-safe' operation.

Ordering Information:

Part #	Description	Replaces	Trade Price
11784	IFS-993 Monitored strobe/sounder driver card	8055 – IFS-993B	\$80

If you have any question please do not hesitate to contact me.

Sincerely,



James Edwards
Product Manager